

## RACCORDS A SOUDER


## WELDING COUPLINGS

TYPE PETROLE SCH.40  
ACIER AE 250 :

SCHEDULE 40 STEEL AE 250 :

Réductions concentriques :


Concentric reducers :



3/4" x 1/2" R2015	1" x 1/2" R2515	1" x 3/4" R2520	1"1/4 x 3/4" R3220	1"1/4 x 1" R3225
1"1/2 x 3/4" R4020	1"1/2 x 1" R4025	1"1/2 x 1"1/4 R4032	2" x 3/4" R5020	2" x 1" R5025
2" x 1"1/4 R5032	2" x 1"1/2 R5040	2"1/2 x 1"1/2 R6540	2"1/2 x 2" R6550	3" x 1" R8025
3" x 2" R8050	3" x 2"1/2 R8065	4" x 2" R10050	4" x 3" R10080	

Tes égaux :


Straight tees :



3/4" T20	1" T25	1"1/4 T32	1"1/2 T40	2" T50
2"1/2 T65	3" T80			

Tes réduits :


Reducing outlet tees :



2" x 1" x 2" TR502550	2" x 1"1/4 x 2" TR503250	2" x 1"1/2 x 2" TR504050	3" x 1"1/4 x 3" TR804080	3" x 2" x 3" TR805080
3" x 2"1/2 x 3" TR806580				

Courbes 90° 3D :

90° elbows :



1/2" C15	3/4" C20	1" C25	1"1/4 C32	1"1/2 C40
2" C50	2"1/2 C65	3" C80	4" C100	